



GOVERNMENT OF INDIA  
CENTRAL PUBLIC WORKS DEPARTMENT  
KANNUR CENTRAL SUB-DIVISION – I  
CRPF CAMPUS, ARAVANCHAL (P.O), PERINGOME,  
Payyannur, Kerala  
Ph: 04985 237297



No: 17(1)/KaCSD-1/ 332

Dt. 03/04/2018.


**SAFETY CERTIFICATE**

It is certified that the buildings ( staff quarters and School Building ) and boundary wall of Kendriya Vidyalaya at Vidyanagar was inspected on 13.03.2018 and the buildings are found structurally safe for its intended use.

However it is noticed during the inspection that due to the pre occurred seepage and age of the building, the roof slab ceiling plaster of the school building is in depilated and dangerous condition as it has swollen and separated from the roof with cracks at many places and may fall without any further warning which may cause casualties to the occupants. The following repair works may be carried out for safe use of the building.

1. Stair case roof ceiling plaster is in swollen and separated from roof with cracks.
2. Roof ceiling plaster of passage near girls toilet needs repair
3. Girls' toilet wall plaster found with cracks and need re plastering.
4. Roof plaster of passage near staff room and department of language is found with cracks and may fall at any moment.
5. Beams in passages are found with cracks need repair.


The works may be carried out as early as possible to avoid any untoward incident.

  
Assistant Engineer

Kannur Central Sub Division-1,CPWD  
CRPF Campus,Peringome

Copy to:

1. Executive Engineer, Kannur central division, Kannur
2. Junior Engineer, KaCSD-1

  
03/4/2018